## Kit Contents

1	Laser-cut acrylic mounting plate
8	5/8" aluminum stand-offs
16	4-40 machine screws

Setup

1. Remove the protective paper backing from each side of the acrylic mounting plate
   (If additional/different mounting holes are required, drill these holes before removing protective paper)
2. Mount the stand-offs to the plate using 4-40 machine screws
3. Mount the Prop-1 and AP-8 to stand-offs using 4-40 screws

Accessories

805-00002	14-inch, 3-pin extension cable;	*used to connect the AP-8 to the Prop-1 controller*
805-00750	2.1mm pigtail cable;	*used to power the AP-8 from the Prop-1 V+ and GND terminals*
750-00007	12vdc, 1A power supply;	*provides power for the Prop-1 and AP-8*